

April 10, 2001

Ms. Fran Babin Great Wall Construction 1411 E. Primrose Springfield, MO 65804

Re: Correction of improper plumbing of sump pumps in the basement of the Greek Corner, 940 S. National.

Dear Ms. Babin:

On April 9, 2001 Mr. Jim Kern contacted this office stating that the requested changes to the sump pump discharges, at the 940 S. National, have been completed. Mr. Kern wanted to know if a follow up inspection could be made on April 10, 2001. At approximately 9:50 A.M., on April 10, 2001, personnel from this office inspected the completed work. It appears that the discharges from both sump pumps have been properly routed.

The City of Springfield greatly appreciates your quick response in correcting this problem.

If you have any questions please feel free to contact me at 864-1488.

Yours Truly

Gene Pabst

Pretreatment Inspector

Industrial Pretreatment Program

cc:

Robert R. Schaefer, P.E., Assistant Director of Public Works

Ed Malter, P.E., Superintendent of Sanitary Services

Randy Lyman, Pretreatment Coordinator

Todd Wagner, P.E., Public Works Engineering

940 S. NATIONA

DEPARTMENT OF PUBLIC WORKS

840 Boonville Avenue, P.O. Box 8368 Springfield, Missouri 65801-8368

phone: (417) 864-1900

homepage: springfield.missouri.org/gov e-mail: city@ci.springfield.mo.us

City of Springfield

Memo

To:

Greek Corner (Bears Mall)

From:

Gene Pabst

CC:

Date:

04/05/01

Re:

Meeting with plumber to correct problem

On April 5, 2001, at 9:30 A.M., I met Jim Kern (building maintenance) and Rick (Witt Plumbing) to look at the problem at the Bears Mall. After explaining and looking at the problem the plumber said that he would the two problems correct by this afternoon or tomorrow at the latest. They will contact me when the work has been completed so an inspection can be made of the completed work.





April 3, 2001

Ms. Fran Babin Great Wall Construction 1411 E. Primrose Springfield, MO 65804

Re: Improper plumbing of sump pumps in the basement of the Greek Corner, 940 S. National.

Dear Ms. Babin:

Personnel from this office made an inspection of the Greek Corner on March 3, 2001 (10:00 A.M.) as the result of a complaint this office received on March 2, 2001. The complaint stated that their was red colored water being pump to the curb on Belmont St. just East of National Ave. Upon investigation it was found that the red water is coming from a silk screen cleaning operation in the basement of the Greek Corner. The water from this operation should not be discharged to the storm sewer, but should be rerouted to the sanitary sewer. The sump pump that is being used to pump this water to the curb should stay in place to allow it to pump groundwater as it was originally designed to do. Also, during the inspection a second sump pump was found. This sump pump is designed to pump groundwater to the storm sewer also. The discharge from this sump pump is currently going to the sanitary sewer and not to the storm sewer. This is a violation of the Springfield City Code, Chapter 120, Wastewater Regulations, Section 120-112(18) "Restricted Discharges." (Please find the enclosed copy of Chapter 120). The discharge from the second sump pump should be removed from the sanitary sewer and rerouted to the storm sewer.

The City is requesting these corrections be made within 15 days. Please notify this office when the required work is completed so another inspection can be to verify that the problem has been corrected.

If you have any questions or would like for me to meet you at the Greek Corner, to discuss the problem, you can contact me at 864-1488.

(417) 864-1900

Yours Truly

Pretreatment Inspector

Industrial Pretreatment Program

cc:

Robert R. Schaefer, P.E., Assistant Director of P Ed Malter, P.E., Superintendent of Sanitary Serv Randy Lyman, Pretreatment Coordinator Todd Wagner, P.E., Public Works Engineering

940-B S, NATIONA |
DEPARTMENT OF PUBLIC W
840 BOONVILLE AVENUE, P.O. BOX 8368 SPRINGE



Screenprinting /Monogramming





Public Works Department Sanitary Services Division Industrial Pretreatment Section Complaint/Report Form

	Date 4/2/01
Report From:	Received By: R. Lynan
□Citizen □	Referred To: G. PABST
□Public Information Office	Date of Incident: 4/2/01
☐ Health Department	
□Fire Department	
☐Mo. Dept. Of Natural Resources	4
Other FRANK KEYES- 510	SN SHOP
Complainant Information:	Responsible Party Information:
Name	Name UNIV. STUDENT MALL
Address	Address 940 S. NATIONAL
Phone	Address 940 5. NATIONAL Phone 883-0202
Directions(if needed):	
Possible contamination of: sanitary sewer	
□ surface water Location:	
Other pertinent information:	
Who to contact: ☐ Mo. Dept. of Natural Resources 417-891-4300(Regional Composition of Natural Resources 573-634-2436(Emergencomposition of Natural Resources 573-751-7929(Response of U.S. Environmental Protection Agency 913-281-0991) ☐ City Fire Department 864-1500 ☐ City Police Department 864-1708 ☐ City Utilities 831-8311	cites only) City Sewer Cleaning 864-1923 City Sewer Repair 864-1923 City Street Division 864-1965 Chemtrec 1-800-424-9300 National Response Center 1-800-424-8802 Other
Details of Incident: "Sum P Punp"	DISCHARGE TO CURB + CONTAMINATED WITH NING CONCRETE IN STREET.
GUTTER ON BELMONT 15	CONTAMINATED WITH
REDDISH MATERIAL SYM	NING CONCRETE IN STREET.
The second secon	
W.S.	
Action needed: INVESTIGATE AM	UD SEE WHAT THEY MAY
HEALTH DEPT, BUT BE SU	mp. CAN REFER to
HEALTH DEPT, BUT BE SU	LRE SUMPPUMP IS NOT
CONNECTED TO SANITARY	SENER AS A SOLICTION.
Sump pund WAS DESIGNED FO	BR GROUNWATER REMOUND
FROM BASEMENT + PERIA	METER DRAINS, STORAGE WATER
TO SANITARY SEWER PROHIB	RICTED BY CHAPTER 120, RICTED DISCHARGES" D
Section - 112 (18), "REST	RICTED DISCHARGES" D
	4

(page 1 File by street address 940 S. NATIONAL C:\MyFiles\Complaint form.wpd

1006006702□ CY 10 BK 6 1006-0067-02 JESTER WILLIAM R 940 DBA UNIVERSITY STUDENT MALL 1411 E PRIMROSE STE A SPRINGFIELD MO 65804-437	S NATIONAL 2/01 11:16:17 65804 PUBLISH: YES
ACCOUNT STATUS 01	INITIAL DATE 9/29/98
SVCS PRES 11 31 00 00 00 00 00 SW	NUMBER OF ACTIVE SERVICES 2
NUMBER SVCS SIGNED FOR 2	AUTOMATIC CONN CODE
SPECIAL HANDLING CODE	PENALTY INHIBIT CODE
PREVIOUS CHANGE TYPE 330	PREVIOUS CHANGE DATE 2/12/01
TRANSFER AMOUNT \$.00	TAX CLASS CODE 2
MAINTENANCE DATE 9/30/98	TRANSFER ACCT NO
NO AUTO DISCONNECTS 0	TAX LOCATION Springfield
CURRENT ACCOUNT ENTRY	TRNSF FNL AMT TO ACCTNO
CURRENT AEF DATE 10/1998	MAP NUMBER SEC03
CURTAILMENT CODE 4	TOTAL ACCOUNT ENTRY 25.00
PHONE	SIC
	SOCIAL SECURITY NUMBER 496-50-2642
	PAGER, MOBILE, MSG. #
	ROUTE H

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF	FILE	DATE	July 9, 1982	
DEPARTMENT				

RE: 940 South National

This office inspected the discharge at the building's ground water sump pits. Jerry King, Building Regulations Department, informed this office of a possible illegal discharge. A basement stool and shower were tributary to the pit that collects subsurface floor and footing drains. The sanitary facilities are now tributary to a sewage ejector and are pumped to the sanitary sewer. The building has two footing drain sumps. The west sump (noted above) is tributary to the storm sewer via a curb outlet. The second, located east of the first, is tributary to the sanitary sewer. While this is an illegal connection, this office chose not to require disconnection due to the following:

- The west sump is significantly lower in elevation and keeps the cone of depression below the east sump pump intake.
- 2. If the curb outlet should freeze, as it has in the past, the water will flood the basement if not pumped to another location.
- 3. Even if removed from the sanitary sewer, it could be replaced very easily.

SIGNED.....

940 S. NATIONAL